AUSTRIA MOTORSPORT

Herbstrallye Dobersberg
10.10. – 11.10.2025

Datum:/Date	**Samstag/Saturday, 11. Oktober 2025**	Zeit:/Time:	**9:15**
Betreff:/Subject:	**Entscheidung/Decision No. 2**	Document No.:	**2.2**
Von:/From:	**Den/The Stewards**		
An:/To:	**Bewerber und Team Startnummer 11/ Competitors and Crew of Car #11**		
	Seitenanzahl:/Number of pages: 1	Anlagen:/Attachments: 0	

The stewards have received a report from the Scrutineers concerning an incident involving vehicle no. 11 at regrouping area (2A), have examined the incident and have made the following decision:

Facts: Car with start number 11 was found with the fire extinguish system in „test" position

Offence: Art. 53.3.10 of the RSR AMF 2025 - fire extinguish system in rallye car

Decison: fine of € 100.-

Reason: In accordance with Art. 53.3.10 of the AMF RSR 2025, the fire extinguishing system must be active (system armed) at all times during the competition.

During the competition means that the fire extinguishing system must be switched on after leaving the service park, on all connecting stages, on special stages (shakedown, regrouping) and in the parc fermé.

In accordance with Art. 12.8 of the 2025 AMF National Sporting Code,fines shall be paid within 48 hours of their notification (Bank Austria, IBAN AT79 1200 0230 1134 9200). Any delay in making payment may entail suspension during the period a fine remains unpaid

Ing. Günther KREMEL
Chairman of the Stewards

Michael Schriefl
Steward

This decision was handed over to the applicant's representative:

Name (in block letters)	DAVID KOMRCH	Date:	11.10
Position in Team	KONVET SRO TEAM OWNER	Time:	12:40

Published on the official notice board : Date : 11.10.25 Time : 13:00