

| | | |
|--------------------------|---------------------------------------|-------------------------------|
| Document No. 9 | Case Technical non conform - Other | Generated 2026-04-03 16:52 |
|--------------------------|---------------------------------------|-------------------------------|

Event and participant details

| | |
|-----------------------------|---------------------------------------|
| Series Viking Trophy | Session Qualifying Practice |
| Event venue Vojens | Kart No. 114 |
| Class MINI | Driver TIM HANSLER |
| Entrant KRAFT MOTORSPORT | Driver nationality GER |
| Entrant nationality GER | Event date 2026-04-03 - 2026-04-05 |

Fact

The Stewards received a report from the Scrutineers that the Driver mentioned above entered the Parc Ferme after the session mentioned above and was found with a non-conform Exhaust Socket (Restrictor).

Reason

The Stewards received a report from the Scrutineers that the Driver mentioned above entered the Parc Ferme after the session mentioned above and was found with a non-conform Restrictor (exceeded the max inner diameter of 22,10mm). After reviewing the evidence, hearing from the Driver and the Entrant's representative, the Stewards have decided that the Driver failed to respect Art. 6.15 of the 2026 Rotax Global Technical Regulations and Art. 8 of the 2026 Rotax Global Sporting regulations. And take their decision according to Art. 12.3 & 12.4 of the 2026 FIA International Sporting Code.

Decision

Disqualification of the session

Wim Cools (BEL)
(Chairman)

Peter Thornemann (DEN)
(Steward)

Flemming Olsen (DEN)
(Steward)

NOTIFICATION TO THE RELEVANT ENTRANT

I undersigned: _____
personal name

Representing the Entrant: KRAFT MOTORSPORT

Certify that I have been notified of document No. **9** of the Stewards of the Meeting.

Date: 03/04/26 Time: _____ Signature: _____