

Document No. <b>19</b>	Case Technical non conform - Other	Generated 2026-04-04 15:42
---------------------------	---------------------------------------	-------------------------------

## Event and participant details

Series Viking Trophy	Session Race 9 Heat 2
Event venue Vojens	Kart No. 341
Class SENIOR	Driver PATRICK RASMUSSEN
Entrant FIRST RACEPOINT	Driver nationality DEN
Entrant nationality DEN	Event date 2026-04-03 - 2026-04-05

## Fact

The Stewards received a report from the Scrutineers that the Driver mentioned above entered the Parc Ferme after the session mentioned above and was found with a non-conform Carburettor.

## Reason

The Stewards received a report from the Scrutineers that the Driver mentioned above entered the Parc Ferme after the session mentioned above and was found with a non-conform Carburettor. After reviewing the evidence, hearing from the Driver and the Entrant's representative, the Stewards have decided that the Driver failed to respect Art. 6.10 of the 2026 Rotax Global Technical Regulations and Art. 8 of the 2026 Rotax Global Sporting regulations. And take their decision according to Art. 12.3 & 12.4 of the 2026 FIA International Sporting Code.

## Decision

Disqualification from session

Wim Cools (BEL)  
(Chairman)

Peter Thornemann (DEN)  
(Steward)

Flemming Olsen (DEN)  
(Steward)

### NOTIFICATION TO THE RELEVANT ENTRANT

I undersigned: \_\_\_\_\_  
personal name

Representing the Entrant: FIRST RACEPOINT

Certify that I have been notified of document No. **19** of the Stewards of the Meeting.

Date: 04/04/26 Time: \_\_\_\_\_ Signature: \_\_\_\_\_