



---

**Stewards Decision No. 1 / Odločitev žirije št. 1**

**Doc. No.: 2.4**

**From: the Stewards**

**Date: 23. 8. 2025**

**To: AMD Vili**

**Posadka št. 23 / Crew No. 23**

**Time: 8:30**

---

The Stewards having received a report from Chief Scrutineer, have considered the following matter and determine the following:

Žirija je prejela poročilo glavnega tehničnega komisarja, proučila naslednjo zadevo in ugotovila naslednje:

Fact: Control unit of the extinguisher was not in operating position in prestart area control of SS 1.

Offence: Breach of Article 253.7.2, Appendix J to the 2025 FIA International Sporting Code.

Decision: In accordance with Art. 12.8. of ISC (art. 12.5. AS SLO Sporting Regulations) to levy a fine of 200 EUR on Competitor.

The payment of the fine will have to be done on the following bank account: Auto Sport Federation of Slovenia — AS SLO Koprška ulica 98, Ljubljana, IBAN 0700 0000 3851 378, SWIFT: GORES12X.

In accordance with art. 12.6. of FIA ISC fines should be paid within 48 hours of their notification. Any delay in making payment may entail Suspension during the period a fine remains unpaid.

Reason: Fire extinguisher system is a major safety item to protect the crew in case of fire in the car and it is essential for the crew 's safety.

From the moment the Crew leaves its service position in Service park the extinguisher system must be switched in operating mode.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards in accordance with Article 15 of the FIA ISC and Article 9. I. 1. of the FIA Judicial and Disciplinary Rules, within the applicable time limits.

**Dejstvo:** Krmilna enota gasilnega aparata ni bila v aktivnem položaju ob kontroli na HP 1.

**Prekršek:** Kršitev člena 253.7.2, Dodatka J FIA Mednarodnega športnega pravilnika 2025.

**Sklep:** V skladu s čl. 12.8. ISC (člen 12.5 Športnega pravilnika AŠ SLO) se tekmovalcu naloži globa v višini 200 EUR.

Plačilo globe je potrebno poravnati na sledeči bančni račun: Zveza za avto Sport Slovenije AS SLO Koprška ulica 98, SI-1000 Ljubljana, IBAN S156 0700 0000 3851 378, SWIFT: GORES12X.

V skladu s členom 12.6. FIA ISC je potrebno globo plačati v roku 48 ur po njihovi prijavi. Kakršna koli zamuda pri plačilu lahko povzroči prekinitvev v obdobju, ko globa ostane neplačana.



Razlog: Sistem centralnega gasilnega sistema je glavni varnostni element za zaščito posadke v primeru požara v dirkalnem vozilu.

Od trenutka, ko posadka zapusti servisno mesto v servisni coni, mora biti sistem za gašenje vklopljen v načinu delovanja.

Tekmovalce opozarjamo, da imajo pravico do pritožbe na nekatere odločitve žirije v skladu s členom 15 FIA ISC in členom 9.1.1. sodnih in disciplinskih pravil FIA v veljavnih rokih.

Miha LEVEC

Chairperson of the Stewards/

Predsednik žirije

Uroš Dolenc

Steward / član žirije

Dino Deljkic

Steward / član žirije

This Decision was notified to the Competitor as below/Tekmovalec je prejel odločitev:

|  |                 |             |        |
|--|-----------------|-------------|--------|
| Name/ime (in block letters/velike tiskane črke): | ZAJC<br>LOGAR ✓ | Date/Datum: | 23.08. |
| Position within the team/Vloga v ekipi:          | co-driver       | Time/Cas    | 9:46h  |
| Signature  |                 |             |        |