

# 1st response training

Fire extinguisher servicing should be carried out once a year to the standard laid down under BS 5306-3:2009. The service procedure involves thorough checking of the fire extinguisher for corrosion and partial or complete discharge.

Reference should be made to the manufacturer's recommendations and instructions for specific information on servicing and recharging. Any fire extinguishers that are deemed unfit for use should be brought to the attention of the user and removed from service.

**Date:30/01/2026**

**Company: Bournemouth & District Car Club**

Number of Extinguishers	Media Type	Service Date	Renewal Date
6	6kg Dry Powder	January 2026	January 2027
6	6Ltr Foam	January 2026	January 2027
1	9kg Dry Powder	January 2026	January 2027
1	9Ltr Foam	January 2026	January 2027

## Certificate of Maintenance

The above fire extinguishers have been serviced by a BAFE certified service technician.

This ensures that the work carried out by the engineer will be of the highest quality and fully compliant with the relevant British Standards.



1<sup>st</sup> Response Training,

8 Kirkham Avenue,

Christchurch,

Dorset, BH23 7LP

07467 149690

[enquiries1stresponse@hotmail.com](mailto:enquiries1stresponse@hotmail.com)