

Sunday, 21 May 2023

Date:

79" Rally Poland
ORLEN
19 – 21 May 2023
12.10 hrs

Bato	••••••••••••••••••••••••••••••••••••••		
Subject:	Stewards Decision No. 4	Document No.:	2.7
From:	The Stewards		
To:	Competitor car no 30 SIMONE BERTOLOTTI Crew: Simone BERTOLOTTI / Federico CAPILLI		
	Number of pages: 2	Attachments:	[]

Time:

The Stewards, having received a report and a photo from the Technical Delegate, have considered the following matter, determine the following:

- **Fact:** During routine checks at the Stop Control zone at the end of SS 9, the car was found with the control unit of the extinguisher system not in operating position.
- Offence: Beach of Article 253-7.2 of Appendix J to the 2023 FIA International Sporting Code

Decision: Fine 1.000 €

In accordance with Article 12.7 FIA International Sporting Code, the payment of the fines must be done online, within 48 hours of their notification, at the following address: https://fiafines.fia.com. Any delay in making payment may entail suspension during the period he fine remains unpaid.

Reason: The competitor was informed accordingly by the Stewards and was given the possibility, if they wished, to bring forward any representations other than having forgotten to activate the extinguisher system. Team Representative confirmed that the Crew accidentally switched the system off.

As stipulated in Article 253-7.2.4 of Appendix J to the 2023 FIA International Sporting Code, the system must work in all positions. Article 253-7.2 of Appendix J to the 2023 FIA International Sporting Code does not specify when the system can be switched on or switched off. For this reason, it must always be active during the rally. Doubtless it must be armed on Special Stages. The fire extinguisher system is a major safety item to protect the crew in case of fire in the car. It is essential for the driver's safety and safety is one of the major concerns by the FIA. Safety remains a key challenge and the FIA is committed to do everything possible to protect, among others, the drivers.

It is further to be noted that the CoC issued Communication No. 2 on Friday 19 May 2023 reminding all competitors about the activation of the extinguisher system. Competitors must always ensure that the system is activated before leaving the service park.

The Stewards therefore concluded that this was a breach of Article 253-7.2 of Appendix J to the 2023 FIA International Sporting Code.

The decision is based on the FIA International Sporting Code Art. 11.9.1, art.11.9.2.a, Art. 11.9.3.a, Art. 11.9.3.f and Art 12.4.1.c.





Competitors are reminded of their right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code and Chapter 4 of the FIA Judicial and Disciplinary Rules, within the applicable time limits.

Uwe M. SCHMIDT (DEU) FIA Chairman of the Stewards

Kostyantyn BEVZ (UKR) FIA Steward

Fukar Bilg

Łukasz BIEGUS (POL) ASN Steward

This decision was notified by SPORTITY to the Competitor's officially nominated representative as below:

Name in block letters	Simone BERTOLOTTI	Date	21.05.2023
Position in the team	Driver	Time	12:20

Published on the Digital Notice Board on 21.05.2023 at 13:35 hrs