







Date: Saturday, 29th October 2022 Time: 12.25 hrs

Subject: STEWARDS DECISION NO. 02 Document No.: 2.5

From: The Stewards

To: Competitor no 25 - TURKISH AUTOMOBILE SPORTS FEDERATION

Crew: Ali Turkkan / Ahmet Burak Erdener

Number of pages: 2 Attachments: [...]

The Stewards, having received a report from the Technical Delegate, summoned and heard the team representative, (summons No 2, Doc 4.2), have considered the following matter, determine the following:

Fact: During routine checks at the stop of SS8, the car was found with the fire extinguisher

system not activated.

Offence: Breach of Article 253.7 of Appendix J 2022 in conjunction with Art. 32.2.1 of FIA 2022

RRSR.

Decision: Fine of 250 €.

In accordance with Article 12.8 FIA International Sporting Code, the payment of the fines must be done online, within 48 hours of their notification, at the following address: https://fiafines.fia.com. Any delay in making payment may entail Suspension during the period a fine remains unpaid.

Reason:

The team representative was informed accordingly by the Stewards and was given the possibility, to bring forward any representations other than having forgotten to activate the extinguisher system. The representative first explained that after asking the co-driver that the crew was switching of the system after each stage.

As stipulated in Article 253.7 of Appendix J to the 2022 FIA International Sporting Code, the system must work in all positions. Article 253.7 of Appendix J to the 2022 FIA International Sporting Code does not specify when the system can be switched on or switched off. For this reason, it must always be active during the rally.

The fire extinguisher system is a major safety item to protect the crew in case of fire in the car. It is essential for the driver's safety and safety is one of the major concerns by the FIA. Safety remains a key challenge and the FIA is committed to do everything possible to protect, among others, the drivers.

It is further to be noted that the Stewards issued Communication No. 2 on 26th October 2022 reminding all competitors about the activation of the extinguisher system. Competitors must always ensure that the system is activated before leaving the service park.

The Stewards therefore concluded that this was a breach of Article 253.7 of Appendix J to the 2022 FIA International Sporting Code and cannot see any reason why the system should not have been switched on.

The decision is based on the FIA International Sporting Code Art. 11.9.1, art.11.9.2.a, Art. 11.9.3.a, Art. 11.9.3.f, and Art 12.4.1.c.









Competitors are reminded of their right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code and Article 9.1.1 of the FIA Judicial and Disciplinary Rules, within the applicable time limits.

In accordance with Article 15.4.2.b the Stewards set the time limit for the notification of the intention to appeal to 29.10.2022 - 14.00 hrs.

Uwe M. SCHMIDT (GER)

FIA Chairperson of the Stewards

Edoardo DELLEANI (ITA)

FIA Steward

Alain MAHÉ (FRA)

ASN Steward

This decision was notified by SPORTITY to the Competitor's officially nominated representative as below:

Name in block letters	MURAT BOSTANCI	Date	29.10.2022
Position in the team	Rally4 Team Representative	Time	12.30 h

Published on the Digital Notice Board on 29.10.2022 at 12.35 hrs

