Navara Track Walk 2026

GOODYEAR®


2026 – Navarra Track Walk:

- The surface is changing several times across the lap.
  - Old rough surface: Approach of T2 until exit of T3; Entry T8 until exit T10; Entry T15 until finish line
- In general low kerbs with sausage kerbs on the inside of low speed corners.
- No banking and some elevation changes across the circuit.
- Quite bumpy start/finish straight.
- Exit of T8 has some broken tops of the kerbs and broken concrete end of this kerb.
- Expected level of wear by surface roughness: medium

GOODYEAR PROPRIETARY AND CONFIDENTIAL

Track Map:


Circuito de Navarra




GOODYEAR PROPRIETARY AND CONFIDENTI

Turn 1:


Entry



Apex




Exit




Turn 2:


Entry



Apex




Exit




Turn 2 - continued:

Apex kerb




Turn 3:

Entry



Apex



Exit




Turn 4:


Entry



Apex




Exit




Turn 5:


Entry



Apex




Exit




GOODYEAR PROPRIETARY AND CONFIDENTIAL

Turn 6:

Entry




Apex




Turn 7:

Entry



Exit




Turn 8:


Entry



Apex



Exit



Turn 8 - continued:

Exit kerb



Exit kerb




End of kerb




Turn 9:

Entry



Apex




Exit




Turn 10:

Apex




Exit




Turn 11:

Entry



Apex




Turn 12:

Apex




Exit



Turn 13:

Entry




Apex




Turn 14:


Entry



Apex



Exit




Turn 15:

Entry



Apex




Exit



Turn 16:


Entry



Apex




Exit




Turn 17:


Entry



Apex



Exit



THANK YOU

