

Date / Datum: 14.03.2026

Time / Zeit: 07:30

Subject / Betreff: DECISION no. 3
ENTSCHEIDUNG Nr. 3

Doc. No. / Dok. Nr.: 2.6

From / von: the Stewards / den Stewards

To / an: Bewerber/ Competitor CATHERINE RADULESCU Fahrzeug/Car No . 58

Crew Catherine Radulescu / Bogdan Mineo

Numbers of pages / Seitenanzahl: 2

Attachments / Anlagen: 0

Die Stewards haben einen schriftlichen Bericht des Cheftechnikers (Dok. 6.4), die Fotodokumentation, den folgenden Sachverhalt geprüft und entschieden:

Fakten: Während Routinekontrollen im parc ferme (ZK7b-ZK7c) wurde das Fahrzeug mit der Startnummer 58 mit einem nicht im Bereitschaftsmodus befindlichen Feuerlöschsystem vorgefunden.

Vergehen: Verstoß gegen Art. 53.3.10 der AMF RSR 2026

Entscheidung: Geldstrafe von 250 EUR für den Bewerber

Begründung: In Artikel 253-7.2.4 des Anhang J zum Internationalen Sportgesetz 2026 und in Artikel 53.3.10 der AMF RSR 2026 wird festgelegt, dass das Feuerlöschsystem zu jedem Zeitpunkt während einer Rallye einsatzbereit sein muss. Das Feuerlöschsystem ist eine zentrale Sicherheitseinrichtung für die Crew im Falle eines Brandes essenziell für die Sicherheit der Crew. Sicherheit bleibt eine zentrale Herausforderung, und die AMF ist entschlossen, alles zu tun, um die Besatzung zu schützen. Der Bewerber muss sicherstellen, dass das System vor Verlassen des Serviceparks, aktiviert ist.

Die Stewards kommen zur Entscheidung, dass das ein Verstoß gegen Art. 53.3.10 AMF RSR 2026 und Art. 253-7 des Anhang J zum Internationalen Sportgesetz der FIA 2026 darstellt.

Die Entscheidung basiert auf den Artikeln Art. 11.9.1, Art. 11.9.2.a, Art. 11.9.3.a, Art. 11.9.3.f und Art. 12.4.1.c des International Sporting Code 2026.

Der Bewerber wird darauf hingewiesen, dass er das Recht hat, gegen bestimmte Entscheidungen der Stewards gemäß Artikel 15 des Nationalen Sportgesetzes 2026 der AMF-Berufung einzulegen.

Gemäß Art. 12.8 des Nationalen Sportgesetzes 2026 der AMF sind Geldstrafen innerhalb von 48 Stunden nach ihrer Bekanntgabe zu zahlen (Bank Austria, IBAN AT79 1200 0230 1134 9200). Jede Verzögerung bei der Zahlung kann zu einer Suspendierung für den Zeitraum führen, in dem die Geldstrafe unbezahlt bleibt.

The Stewards, having received a report from the Chief Scrutineer (Doc. 6.4), having checked the photo evidence, and having considered the following matter, determine the following:

Facts: During routine checks in the parc ferme area (TC7b -TC 7c), car number 58 was found with the fire extinguishing system not in operating mode.

Offence: Breach of Art. 53.3.10 of the AMF RSR 2026

Decision: To impose a penalty of **EUR 250** on the competitor

Reason: According to Article 253-7.2.4 of Appendix J to the FIA International Sporting Code 2026 and Article 53.3.10 of the AMF RSR 2026, the fire extinguishing system must always be ready for use during a rally.

The fire extinguishing system is a key safety device and is essential for the safety of the crew in the event of a fire. Safety remains a major challenge, and the AMF is committed to doing everything possible to protect the crews.

The competitor must ensure that the system is activated before leaving the service park at every time.

The Stewards therefore conclude that this constitutes a breach of Art. 53.3.10 AMF RSR 2026 and Art. 253-7 of Appendix J to the FIA International Sporting Code 2026.

This decision is based on Art. 11.9.1, Art. 11.9.2.a, Art. 11.9.3.a, Art. 11.9.3.f and Art. 12.4.1.c of the FIA International Sporting Code 2026.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the National Sporting Code within the applicable time limits (document can be found at <https://www.austria-motorsport.at>).

In accordance with Art. 12.8 of the AMF National Sporting Code 2026, fines must be paid within 48 hours of notification (Bank Austria, IBAN AT79 1200 0230 1134 9200). Any delay in payment may result in a suspension for the period during which the fine remains unpaid.



Christian SINGER
Vorsitzender der Stewards



Josef RIEGER
Steward



Alfred PIESINGER
Steward

Received by the Competitor:

Signature: 

Date: 14.3. Time: 9:48