



Data: 29.10.2022

Ora: 14:50

Subject: DECIZIA NR. 6

Nr. Doc. 2.7

Emis de/ Issued By: Colegiul Comisarilor Sportivi / *Stewards Panel*

In atentia/ In attention to: Concurentul nr.588 *Competitor No 588* –Oleksandr Melnychuk/Liubomyr Sumakov

Nr. Pagini/ No Pages: 2

Comisarii Sportivi au primit o informare a Sefului Verificarilor Tehnice (Informare Nr.4) cu privire la verificarile efectuate in Stop PS 6, au analizat situatia prezentata si au decis urmatoarele:

Fapta: Nu avea scoasa siguranta extingtorului automat in Stop PS 6

Ofensa: Incalcare a art. 53.1 din regulamentul CNRB coroborat cu art. 253 - 7.2 din anexa J din CSI

Decizia: Amenda de 500 lei platita catre FRAS; termen plata 01.11.2022 ora 12:00

Motiv: La verificarile tehnice din timpul competitiei, in cursul zilei de vineri, 29.10.2022, Comisarii Tehnici au verificat elementele de siguranta ale automobilelor de concurs si echipamentele concurentilor in Stop PS 6. Masina echipajului nr. 588 – Oleksandr Melnychuk/Liubomyr Sumakov nu avea cuiul de siguranta scos.

Dupa cum se prevede la articolul 253-7.2.4 din anexa J din CSI FIA 2022, sistemul de stingere trebuie sa functioneze in toate situatiile. Articolul 253-7.2 din Anexa J a CSI FIA 2022 nu specifica cand sistemul poate fi pornit sau oprit. Fara indoiala trebuie sa fie armat pe probele speciale, ceea ce nu a fost cazul pentru echipajul mentionat.

Sistemul de stingere a incendiilor este un element major de siguranta pentru protejarea echipajului in caz de incendiu in automobilele de competitie. Este esential pentru siguranta echipajului, iar siguranta este una dintre preocuparile majore ale FRAS. Concurentii trebuie sa se asigure intotdeauna ca sistemul este activat inainte de a parasi parcul de service.

Concurentilor li se reaminteste ca au dreptul de protest impotriva deciziei Comisarilor, in concordanta cu Art. 15 din Codul Sportiv International si Art. 9.1.1 din Regulamentul Judiciar si Disciplinar FIA, in termenul aplicabil.

The Stewards received a briefing from the Head of Technical Checks(InformationNo.4) on the checks carried out in Stop PS 6, analysed the situation presented and decided the following:

Fact: No fire extinguisher fuse removed in Stop PS 6

Offence: Infringement of Art. 53.1 of the CNRB Regulation in conjunction with Art. 253 - 7.2 of Annex J of the CIS

Decision: 500 lei fine paid to FRAS; payment deadline 01.11.2022 12:00 noon

Motive: During the technical checks during the competition, on Friday 29.10.2022, the Technical Stewards checked the safety elements of the competition cars and the competitors' equipment in



Stop PS 6. The car of crew No. 588 - Oleksandr Melnychuk/Liubomyr Sumakov did not have the safety pin removed.

As stated in article 253-7.2.4 of the CSI FIA 2022 Annex J, the extinguishing system must work in all situations. Article 253-7.2.2 of Annex J of the CSI FIA 2022 does not specify when the system may be switched on or off. It must undoubtedly be armed on special events, which was not the case for the crew mentioned.

The fire extinguishing system is a major safety element to protect the crew in case of fire in competition cars. It is essential for the safety of the crew, and safety is one of the major concerns of the FRAS. Competitors must always ensure that the system is activated before leaving the service park.

Competitors are reminded that they have the right to protest against the Stewards' decision, in accordance with Art. 15 of the International Sporting Code and Art. 9.1.1 of the FIA Judicial and Disciplinary Regulations, within the applicable time limit.

Florin CALANGEA

Razvan RATIU

Rares FLORESCU

Presedinte CCS

Membru CCS

Membru CCS

Decizie trimisa catre echipaj in data de.....ora..... prin intermediul Ofiterului de Relatii cu Concurrentii.

Publicata pe panoul de afisaj Sportity in data dela ora