

Date: 11/10/2023

Time: 1740hrs

Subject: COMMUNIQUE NO: 1

From: The Clerk of the Course
To: All competitors / crew members
Number of pages: 2
Attachments: 1

Approved: Clerk of the Course Michael Clements – 11/10/2023

Testing Update

There has been a change to the testing maps and the direction to get to them from The Bend Service Park. The management do not want us travelling past the Caravan Park early in the morning, so we have been advised we need to enter off the Mallee Highway. As per the attached diagram, you will need to exit The Bend Motorsport Park at the OTR exit and travel North towards Tailem Bend, then turn right onto the Mallee Highway towards Lameroo/Pinnaroo and then turn right back into The Bend Motorsport Park.

Due to the large than expected number of testing crews, we have split the testing track into 2, and added additional distance to the test track 2. The transport back from test track 2 is a bit stoney, but passable by a normal car so should be fine for competition vehicles. Please drive carefully across this road so you don't dig it up and find more rocks for fellow competitors.



Michael Clements
Clerk of the Course

Attachment 1

