



May 17, 2025

### 2025 Oregon Trail Rally Steward Decision #3

Having received a report from the ARA Technical Director which was confirmed by the Chief of Scrutineering that the passenger window of car 116 was down more than 2" on Special Stage 1, the stewards have made the following decision.

This is a violation of RCR 6.4.5 which, as an improper procedure infraction, is referred to the stewards for investigation. The stewards may impose penalties as specified in GCR 7.

The stewards have talked with the crew and determined that the window, held in place by friction, fell down on stage. The window has been secured so this should not happen again.

No penalty is being applied at this time, but the crew has been informed that if this happens again it will result in a 10-minute penalty.

A handwritten signature in black ink, appearing to read 'JBNiday', with a stylized flourish at the end.

J.B. Niday - Sr. Steward

A handwritten signature in black ink, appearing to read 'Rob Bohn', with a long, horizontal flourish extending to the right.

Rob Bohn – Event Steward