

---

Date:	<b>Sunday, 30<sup>th</sup> July 2023</b>	Time:	<b>11.10 hrs</b>
Subject:	<b>Stewards Decision No. 3</b>	Document No.:	<b>2.7</b>

---

From:	<b>The Stewards</b>
To:	Competitor of car No. 72 TEMPO SRL Crew: Fabio ANGELUCCI / Massimo CAMBRIA

---

Number of pages:	2	Attachments:	0
------------------	---	--------------	---

---

The Stewards, having received a report from the FIA Technical Delegate, summoned the Crew (Summons No. 2, Doc 4.2), have considered the following matter and determine the following:

**Fact:** During routine checks at the Stop Control zone at the end of SS8, car No. 72 was found with the control unit of the extinguishing system not in operating position.

**Offence:** Breach of Article 253.7.2 of Appendix J 2023 in conjunction with Art. 32.2.1 of 2023 FIA Regional Rally Sporting Regulations.

**Decision: Fine of € 1000**

In accordance with Article 12.8 FIA International Sporting Code, the payment of the fines must be done online, within 48 hours of their notification, at the following address: <https://fiafines.fia.com>. Any delay in making payment may entail Suspension during the period a fine remains unpaid.

**Reason:** The drivers were informed accordingly by the Stewards and was given the possibility, if they wished, to bring forward any representations other than having forgotten to activate the extinguishing system.

The Competitor informed that he would not make any further representations.

As stipulated in Article 253.7.2.4 of Appendix J to the 2023 FIA International Sporting Code, the system must work in all positions. Article 253.7.2 of Appendix J to the 2023 FIA International Sporting Code does not specify when the system can be switched on or switched off. For this reason, it must always be active during the rally.

The fire extinguishing system is a major safety item to protect the crew in case of fire in the car. It is essential for the driver's safety and safety is one of the major concerns by the FIA. Safety remains a key challenge and the FIA is committed to do everything possible to protect, among others, the drivers.

**It is further to be noted that the Clerk of the Course issued Communication No. 02 on 17<sup>th</sup> July 2023 reminding all competitors about the activation of the extinguishing system. Additionally, the reminder of the same Communication was issued on 28<sup>th</sup> July 2023.** Competitors must always ensure that the system is activated before leaving the service park.


The Stewards therefore concluded that this was a breach of Article 253.7.2 of Appendix J to the 2023 FIA International Sporting Code.

The decision is based on the FIA International Sporting Code Art. 11.9.1, Art.11.9.2.a, Art. 11.9.3.a, Art. 11.9.3.f, and Art 12.4.1.c.


Competitors are reminded of their right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code and Chapter 4 of the FIA Judicial and Disciplinary Rules, within the applicable time limits.



**Uwe M. SCHMIDT (DEU)**  
FIA Chairperson of the Stewards



**Emilia ABEL (EST)**  
FIA Steward



**Angelo Raffaele PELILLO (ITA)**  
ASN Steward

This decision was notified by SPORTITY to the Competitor's officially nominated representative as below:

<i>Name in block letters</i>		Date	<b>30.07.2023</b>
<i>Position in the team</i>		Time	<b>11:25</b>

**Published on the Digital Notice Board on 30.07.2023 at 11:30 hrs.**