
Date / Datum: 17.07.2026

Time / Zeit: 20:30

Subject / Betreff: COMMUNICATION no.3
KOMMUNIKATION Nr. 3

Doc. No. / Dok. Nr.: 2.3

From / von: the Stewards / den Stewards

To / an: Startnummer 45 / Traussing Thomas/ Stampel Bianca Marina
Team Stengg Motorsport

Numbers of pages / Seitenanzahl: 2

Attachments / Anlagen: 1

Die Stewards haben einen schriftlichen Bericht des Cheftechnikers (Dok. 6.2), die Fotodokumentation, den folgenden Sachverhalt geprüft und entschieden:

Fakten: Bei der Kontrolle der Feuerlöschanlagen im Regrouping 2A wurde das Fahrzeug mit der Startnummer 45 mit einem nicht im Bereitschaftsmodus befindlichen Feuerlöschsystem vorgefunden.

Vergehen: Verstoß gegen Art. 53.3.10 der AMF RSR 2026

Entscheidung: Geldstrafe von 250 EUR für den Bewerber

Begründung: In Artikel 253-7.2.4 des Anhang J zum Internationalen Sportgesetz 2026 und in Artikel 53.3.10 der AMF RSR 2026 wird festgelegt, dass das Feuerlöschsystem zu jedem Zeitpunkt während einer Rallye einsatzbereit sein muss.

Die Stewards kommen zur Entscheidung, dass das ein Verstoß gegen Art. 53.3.10 AMF RSR 2026 und Art. 253-7 des Anhang J zum Internationalen Sportgesetz der FIA 2026 darstellt.

Der Bewerber wird darauf hingewiesen, dass er das Recht hat, gegen bestimmte Entscheidungen der Stewards gemäß Artikel 15 des Nationalen Sportgesetzes 2026 der AMF-Berufung einzulegen.

Gemäß Art. 12.8 des Nationalen Sportgesetzes 2026 der AMF sind Geldstrafen innerhalb von 48 Stunden nach ihrer Bekanntgabe zu zahlen (Bank Austria, IBAN AT79 1200 0230 1134 9200). Jede Verzögerung bei der Zahlung kann zu einer Suspendierung für den Zeitraum führen, in dem die Geldstrafe unbezahlt bleibt.

The Stewards, having received a report from the Chief Scrutineer (Doc. 6.2), having checked the photo evidence, and having considered the following matter, determine the following:

Facts: During the inspection of the fire extinguishing systems in Regroup 2A, car number 45 was found with its fire extinguishing system not in standby mode.

Offence: Breach of Art. 53.3.10 of the AMF RSR 2026


Decison: To impose a penalty of **EUR 250** on the competitor

Reason: According to Article 253-7.2.4 of Appendix J to the FIA International Sporting Code 2026 and Article 53.3.10 of the AMF RSR 2026, the fire extinguishing system must always be ready for use during a rally.


The Stewards therefore conclude that this constitutes a breach of Art. 53.3.10 AMF RSR 2026 and Art. 253-7 of Appendix J to the FIA International Sporting Code 2026.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the National Sporting Code within the applicable time limits (document can be found at <https://www.austria-motorsport.at>).

In accordance with Art. 12.8 of the AMF National Sporting Code 2026, fines must be paid within 48 hours of notification (Bank Austria, IBAN AT79 1200 0230 1134 9200). Any delay in payment may result in a suspension for the period during which the fine remains unpaid.



Rainer WERNER
Vorsitzender der Stewards



Gerhard LEEB
Steward



Josef RIEGER
Steward

Name (in Blockbuchstaben)	Willi STEN66	Datum:	17-07
Position im Team	Team Manager	Uhrzeit:	2045
Unterschrift			