



DYNAMAX MEDZINÁRODNÉ MAJSTROVSTVÁ SLOVENSKEJ REPUBLIKY AUTOPOLA Jankov vršok 2023 (SVK) - 4. -6.08-2023

ORGANISER: ZO ZTŠČ MOTORSPORT Bánovce nad Bebravou,

ASN: SAMŠ

Date: 5/08/2023

Time: 18.10 hrs

ROZHODNUTIE RŠK č. 2

Document No: **2.12**

OD: Stewards' board /Rada športových komisárov

KOMU: MTB Racing Team, driver No. 31 Marek HÚSKA

Number of pages	1	Attachment(s)	-
-----------------	---	---------------	---

The Stewards, having received a report from the Chief Strutineer, summoned the Driver No. 31, Doc 4.2), have considered the following matter and determine the following:
RŠK prijala správu od HTK a predvolala si jazdcaš.n. 31 nasledne prijala toto rozhodnutie

Fact: During routine checks at the Finish zone at the end 2nd Race, car No. 31 was found with the control unit of the extinguishing system not in operating position.

Pri kontrole v cieľovom priestorepo druhej jazde st.c. 31 nemalo odistený haciaci prístroj.

Offence: Breach of Article 253.7.2 of Appendix J 2023

Porušenie článku 253.7.2 prílohy J MŠP

Decision: Fine of € 25 / Pokuta 25€




payment deadline until 7:00 a.m. on August 6, 2023 /lehota zaplatenia do 07:00hod dňa 6.8.2023

Reason: The fire extinguishing system is a major safety item to protect the crew in case of fire in the car. It is essential for the driver's safety and safety is one of the major concerns by the FIA. Safety remains a key challenge and the FIA is committed to do everything possible to protect, among others, the drivers.

Competitors must always ensure that the system is activated before leaving the service park. The Stewards therefore concluded that this was a breach of Article 253.7.2 of Appendix J to the 2023 FIA International Sporting Code.

Hasiaci systém je hlavným bezpečnostným prvkom na ochranu posádky v prípade požiaru v aute. Je to nevyhnutné pre bezpečnosť jazdca a bezpečnosť je jedným z hlavných záujmov FIA. Bezpečnosť zostáva kľúčovou výzvou a FIA sa zaviazala urobiť všetko, čo je v jej silách, aby okrem iného ochránila jazdcov. Pretekári sa musia vždy pred opustením servisného parkoviska uistiť, že je systém aktivovaný. Športoví komisári preto dospeli k záveru, že ide o porušenie článku 253.7.2 Prílohy J Medzinárodného športového poriadku FIA 2023.

Guidance / Poučenie: The Competitor was reminded of his right to appeal in accordance with Article 15 of the FIA International Sporting Code / Súťažiaci bol poučený o svojom práve odvolať sa v zmysle MŠP FIA článok 15.

[signature 1 / podpis]  Chairman of the Panel / Predseda Pavol KUŠNIER	[signature 2 / podpis]  Steward / Člen Marcin FIEDASZ	[signature 3 / podpis]  Steward / Člen Lubomír ŠIMKO
--	---	--

Prevzatie:

Meno: *LUŠKA MAREK MTB DACH 6*

Súťažiaci: *LUŠKA MAREK*

Zverejnené na oficiálnej informačnej tabuli dňa: *08.08.2023*

Čas

Š.č

o *18:10*

