







2023 F4 SPANISH CHAMPIONSHIP – 04 JEREZ

Date: 23/09/2023 Document Nº: 42B Time: 17:10

From:

The Stewards of the Event

Decision Nº 7

To:

Carlin Motorsport, car 26

The Stewards, a report from Spanish Formula 4 Championship Technical Delegate (document No 5), summoned team representative have considered the following matter, determine the following:

Driver and car No: Alex Ninovic, 26

Competitor: Carlin Motorsport

Time: 16:40h Session: Race 1

Fact: Car 26 has been found on track with the extinguisher system not activated, light green of cockpit panel

was switch off.

Offence: Breach of Article 14 of the Spanish F4 technical regulations.

Decision: Disqualified car No 26 on Race 1 in accordance with Article 16.4 and Article 23.13 of the Sporting

Regulations.

Reason: Having considered the matter extensively, the Stewards determined that is a technical issue and were in breach of Art. 14 of the Technical Regulations and Art. 16.4 and Art. 23.13 of the Sporting Regulations, that the driver must drive the car with the safety equipment working correctly.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards (art. 15 Int'l Sporting Code). According to art. 12.3.4 ISC and art. 14.5c F4 Spanish Championship Sporting Regs.

The Stewards

Thierry DEFLANDRE

Chairman

RACB-1142

Iván FONT

Steward

CD-0046-ESP/CV

JavierMART

CD-1129-ESP/AN

Received by the Competitor:

Signature:

Date: 24/9/23 Time: 18:05